

ISTRUZIONI DI MONTAGGIO

(vedi illustrazioni sul retro)

1. Sguainare il cavo passante e quello derivato e mettere a nudo i conduttori delle fasi da derivare come indicato in fig.1.
2. Rimuovere i grani filettati dai morsetti. Divaricare le fasi del cavo passante ed inserire la morsettiera posizionando ciascuna fase, anche quelle da non derivare, in ognuna delle sedi dei morsetti. Inserire le estremità sguainate dei conduttori del cavo derivato nei morsetti al di sotto dei corrispondenti conduttori del cavo passante. Inserire i grani filettati e stringere applicando la coppia di serraggio appropriata.
3. Divaricare i cavi passante e derivato secondo le proprie esigenze, ed immergere la giunzione nel gel centrando il connettore nell'apposito alloggiamento all'interno del giunto. Facilitare la rottura delle paratie fratturabili, applicando una pressione sui cavi in corrispondenza dei punti di ingresso e di uscita.
4. Chiudere a scatto l'involucro e controllare l'avvenuta fuoriuscita del gel dalle estremità del giunto in corrispondenza dei punti di ingresso e di uscita dei cavi.
5. Inserire e stringere le due fascette fornite a corredo nelle due asole alle estremità del giunto in accordo alla Norma CEI 64-8.

INSTALLATION INSTRUCTIONS


(see illustrations on back side)

1. Remove the external sheath of main and branch cable and strip the conductors to branch as in picture 1.
2. Remove grubs from terminal block. Open wide the cores of the main cable and insert the terminal block positioning each core, also those not to branch, in each connector seat. Put the stripped extremes of the branch cable in the connectors under the corresponding conductors of the main cable. Reinsert grubs and tighten applying adequate torque.
3. Open wide main and branch cables according to own needs and immerse the jointing in the gel, positioning the connector in the apposite seat inside the joint. Ease the breaking of the breakable walls by applying pressure on the cables near cable entry and exit points.
4. Snap-close the enclosure and check the gel has displaced correctly, escaping the enclosure and sealing around the cable at each end.
5. Insert and fasten the cable ties supplied with the kit in the side slits of the joint as per IEC 60364 Standard.

BRANCH JOINT GIUNTO IN DERIVAZIONE



5 × 16 – 35 mm²



5 × 2,5 – 25 mm²

The information contained in these instructions is for use only by installers trained to make electrical power installation and is intended to describe the correct method of installation for this product.

It is the user's responsibility to determine the suitability of the installation method in the user's field conditions.

Le informazioni contenute nelle presenti istruzioni di installazione sono intese ad utilizzo esclusivo degli installatori istruiti alla realizzazione degli impianti elettrici e mirano a descrivere il metodo corretto per l'installazione di questo prodotto. È responsabilità dell'utilizzatore determinare l'idoneità del metodo di installazione rispetto alle condizioni reali sul campo.

ETELEC ITALIA S.p.A.

Via D. De Roberto, 40 - 80143 Napoli
Tel. +39 081 5846610

etelec[®]
electrical technology

SHARK[®] 535Y
GEL INSULATED JOINT



0,6/1 kV
EN 50393



EN 60695-2-11
CEI 20-37/2-1
CEI 20-37/4

MADE IN ITALY
etelec.com

